


Clamber Stack Passo

Excavation Detail



Note.

The balance beams T4539 and T4540 are not fixed to the frame so can be adjusted to fit. Please ensure adequate gaps are left between the timbers so as not to create any entrapments.

This equipment for play areas is manufactured following the codes & practice outlined in the British and European standards and in so doing meets the requirements of BSEN 1176 (general safety and test methods).