

Surface Fixed

Harmony Flowers Page 1 of 2



Instrument Components:

Metric Conversion: 1100mm/" 1.5m/59"


MADE IN BRITAIN BS EN 1176


Installation Instructions




- **1**. Unpack ground fixing legs 3no.
- 2. Lay packaging out on floor or assemble on non-abrasive surface to prevent marking of polished stainless steel.
- 3. Align holes on legs to holes on surface fixing(opposite end to polished domes) and secure in place using 3no.
 M10 x 30mm Screws provided. Tools required TX 45 Driver Bit)
- **4**. Invert assembled frame so flowers are at the top.
- **5.Locate Flowers** in desired location and mark holes to fix to desired surface.
- **6.** Fix to Surface using recommended ground anchors (**Ground Anchors are not supplied**)
- 7. Make sure all fixings are covered and secure using cover caps provided

Weight of heaviest part 6kg (Surface Plate)









Surface Fix Components:







Surface Fixed

Harmony Flowers Page 2 of 2




Instrument Components:

Thread Lock Solution Required




Assembly Guide PPHARMF




Tools: TX 45 Driver Bit

1

Locate the Surface fix Plate into the leg of the instrument.



Fix instrument to Surface fix plate using M10 Screws and use thread locking solution to prevent fixings working loose.



Fix Surface Plate to the ground surface Ground **Anchors Not provided** cover fixings with caps provided







